

MATERIAL SAFETY DATA SHEET - PURCAST HE "B" COMPONENT

SECTION 1 - PRODUCT IDENTIFICATION AND USE

Product Name: PURCAST HE B COMPONENT

Product ID No.: Not Regulated WHMIS Class: D2B

NAERG: 156

Product Use: Polyurethane-Based Chemical Grout

Manufacturer: Resiplast N.V.

B-2160 Wommelgem, Belgium Phone: 011 32 3 844 1120

Supplier: Specton Construction Products Ltd.

12 Wallace Street Unit #2 Acton, ON L7J 2V6

SECTION 2 - HAZARDOUS INGREDIENTS

Ingredient % CAS#

Diphenylemethane <1% 101-68-8

4,4'-diisocyanate

SECTION 3 - PHYSICAL DATA

Physical State: Brown Liquid
Odor & Appearance: Low odor, Oily liquid
Odor Threshold: Not Available
Vapor Pressure: 10⁻⁵ MBAR at 25°C

Vapor Density: 1.0

Evaporation Rate: Low

Boiling Point: >200 ° C

Freezing Point: <0 ° C

pH: Neutral

Specific Gravity: 1.05

Coef. H,O/oil Dist.: <1

SECTION 4 - FIRE AND EXPLOSION DATA

Flammability: No

Means of extinction: CO₂, Halon

Flashpoint >150°C (Pensky-Martens Closed Cup)

SECTION 5 - REACTIVITY DATA

Chemical Stability:

Viscosity Growth <20 mPa.s/month.

Incompatible with other substances containing reactive hydroxyl - and amino - groups; strong alkalines.

Reactivity:

Reacts with water, generates CO_2 .

Beware of pressure build up in closed containers. Reacts vigorously with strong alkali and amines. Hazardous Decomposition Products: None

SECTION 6 - TOXICOLOGICAL PROPERTIES

Route of Entry:

Skin Contact: Yes Skin Absorption: Yes Eye Contact: Yes Inhalation: Yes

Ingestion: Yes
Effects of Acute Exposure:
Skin: Irritation
Eves: Irritation

Inhalation: Coughing, tightening in the chest

Ingestion: Not Available

Effects against Chronic Exposure to Products: Not Available

Exposure Limits: Not Available

Irritancy of Product: Skin, eyes, respiratory tract

Sensitization to Product: Free unreacted monomer will cause

lung sensitization.

Carcinogenicity: Not listed by IARC

Teratogenicity: Not Available ReproductiveToxicity: Not Available Mutagenicity: Not Available Synergistic Products: Not Available

SECTION 7 - PREVENTIVE MEASURES

Personal Protective Equipment:

Use safety goggles.

Use PVC or neoprene industrial gloves.

Use protective clothing, with long sleeves and long pants.

Maintain eye bath in work area.

Engineering Controls:

Use in mechanically ventilated areas.

Do not spray; avoid formation of aerosols.

Beware of pressure buildup in closed containers.

Leak and Spill Procedure:

Absorb with conventional absorbents Dispose according to local regulations.

Waste Disposal:

Absorb with conventional absorbents Dispose according to local regulations. Handling Procedures and Equipment:

Handle with care.

Do not open containers until at working place.

Storage Requirements:

Any convenient location or temperature. Not permanently affected by freezing. Warm up materials prior to use. Special Shipping Instructions: None

SECTION 8 - FIRST AID MEASURES

Skin Contact: Wash with lots of water

Eye contact: Wash with lots of water

and seek medical attention.

NAERG: 156

SECTION 9 - PREPARATION DATE OF MSDS

 Prepared by:
 SPECTON

 Phone:
 1-866-773-2866

 Date:
 January 4, 2018